

### MODEL 8203-3



### WARNING

**WARNING — THE INSTALLATION MUST BE CARRIED OUT BY A QUALIFIED ELECTRICIAN.**

1. Use copper conductors only; 15A, 14AWG to 12AWG
2. Risk of electric shock or death. Disconnect power before installing
3. For installation by a qualified person in accordance with national and local electrical codes


### CAUTION

**PLEASE READ INSTRUCTION BEFORE COMMENCING INSTALLATION AND RETAIN FOR FUTURE REFERENCES.**

**Electrical products can cause death or injury, or damage to property.**

**If in any doubt about the installation or use of this product, consult a competent technician.**

### INSTALLATION



- Remove insulation from conductors 5/8"
- Side Wire — wrap conductor securely around terminal screw. Tighten terminal screws securely, 9-12 pound • inch (1.0-1.4N • m) of torque
- Push Wire — use solid #14 AWG for 15A branch circuit ONLY

ORTECH reserves the right to modify at any time, without notice, any or all of our product's features, designs, components and specifications to meet market changes.